


LOCK-STITCH SEWING MACHINE

HOW TO THREAD THE HEAD OF THE MACHINE

9. Pull the thread downward; hold it taut; slip it into the thread guide (9); then, into the thread eyelet (10) and then down through the thread guide (11) on the needle bar.

Note: These guides have side openings through which to slip the thread for quick threading.



By permission
Copyright, U.S.A., 1952, by the Singer Mfg. Co.
All rights reserved for all countries

Fig. 3
Upper Threading

10. Break thread near the end, moisten and twist the end to a fine point; then, thread through eye of the needle (12) from left to right. Clip whisker at thread end if it interferes with threading.

11. Draw three or four inches of thread through the needle.

Note: The length of thread extending beyond the needle is used to draw up the lower thread as explained in Unit 1GM-Op19.